

## **Daily Update** July 21

## **Repair Work**

Devil's Slide (post mile 39.14)

• Pouring the concrete cap on top of the micropiles started today.



Pouring the micropile wall cap

• Grinding out the existing road surface continued today.



Road surface grinding continues

 Some patching work is required on waler walls C and D which started today.



Surface patching walls C and D

• Trenching work continued for electrical conduits for the slide sensor system. Electrical box installation started also.



Prep. work for electrical box

• Work started to replace the pumping system for well No. 2



Well No. 2 replacement work